

Corporate Office : 28, Community Center, Saket, New Delhi-110017 Tel: 26854492/81, 26536073/74

Fax: 91-11-26854478 E-mail: info@vidpl.com

CLIENTS CERTIFICATE REGARDING COMPLETION/PERFORMANCE OF CONTRACTOR

Name & Address of Client

M/s Vipul Infrastructure Developers Pvt. Ltd.

28, Communikty Centre, Saket, New Delhi – 110 017

Details of works executed by

M/s Suvidha Engineers India Pvt. Ltd. C-37, Sector 57, NOIDA 201301

	1	Name of the work with brief	HVAC-Works, Orchid Square, Sushant
	1	Name of the work with order	Lok, Gurgaon, Haryana.
		particulars	Supply & Installation, Testing
			Commissioning of HVAC WORKS WILL 2 X
			200 TR (Screw Chillers) + 2 x 100 TR
			(Screw Chillers) + 2 x STL Tanks 50 m3
			capacity with three
			condenser Pipes - complete job.
	2	(i) Agreement No. & Date	VIDPL/COR/2002/738 dated 5 th July, 2002
-	3	Date of commencement of work	5 th July, 2002
-	4	Stipulated date of completion	4 th February, 2003
-	5	Actual date of completion	31 st of January, 2003
-	6	Details of compensation levied for	NIL
		delay, if any	
-	7	Tendered amount	Rs.3.15 Crores
+	8	Gross Amount of work completed	Rs.3.00 Crores
+	9	Name and address of the authority	Vipul Infrastructure Developers Pvt. Ltd.
		under whom works executed	28, Community Centre, Saket,
			New Delhi – 110 017
	10	Whether the contractor employed	YES
		qualified Engineer/Overseer during	
		execution of work	
	11	i) Quality of Work (indicate grading	Outstanding/V.Good/Geed/Poor

::> 1	Amount of work paid on reduced	NO
ii)	Amount of work paid on reduced	
	rate basis, if any	
12	i) Did the contractor go for	NO
	arbitration	
ii)	If yes, total amount of claim	N.A
iii)	Total amount awarded	N.A
13	Comments on the capabilities of the	Outstanding/V.Good/Good/Poor
	contractor	
a)	Material supply	As per schedule/delayed/Over delayed
b)	Submission of Shop Drawings	As per schedule/delayed/Over delayed/ not
		eapable for submission
c)	Testing Commissioning	System run smoothly/Defects observed
d)	Submission of As Built Drawing	Submitted/Not Submitted/ not capable for
		submission.
e)	Submission of manual from the	Submitted/Not Submitted.
	equipment manufacturer and	
	operation manual	Outstanding/V.Good/Good/Poor.
f)	Technical proficiency	
g)	Financial Soundness	Outstanding/V.Good/Good/Poor
h)	Mobilization of adequate T & P	Outstanding/V.Good/Good/Poor
i)	Mobilization of manpower	Outstanding/V.Good/Good/Poor
j)	General behaviour	Outstanding/V.Good/Good/Poor

For Vipul Infrastructure Developers Pvt. Ltd.

Moti S. Masand

Director